



Not Ready for Inspection

Issued by Chad Roop, CBO

Acting Building Official

Effective: October 10, 2003

Revised: January 30, 2026

Purpose:

This policy establishes when a rejected inspection is considered Not Ready for Inspection. If a rejected inspection is considered not ready for inspections, re-inspection fees will be applied. However, if there are extenuating circumstances, the inspector has the authority to not apply the re-inspection fee in conjunction with the rejection.

The following guideline is to be used to determine when to apply a Not Ready for Inspection fee.

Table with 2 columns: All Inspections (listing required documents, zoning, etc.) and Slab (listing site preparation, plumbing, electrical, etc.).